



SwemaMan 60 Instructions

vers 1.04 MB20111013



SWEMA AB
Pepparv. 27
SE-123 56 FARSTA
Tel: +46 8 94 00 90
Fax: +46 8 93 44 93
E-mail: swema@swema.com
Web site: www.swema.com

Contents:

1. Introduction.....	1
2. Technical data.....	1
3. Start of instrument.....	1
4. Calculation of air velocity.....	2
5. Data transfer to PC.....	2
6. Alter settings by PC.....	3

1. Introduction

SwemaMan 60 measure differential pressure or air velocity when connected to a pitot static pipe. Differential pressure displays in Pa and air velocity in m/s or fpm. Two easily changeable (regular or rechargeable) AA-batteries are used. A 220V adapter (part no. 763.050) can be used, but doesn't charge the batteries.

2. Technical data

Differential pressure: -300... 5000Pa

Air velocity: 2.0...91 m/s, 400...17900 fpm at 20°C, 1013hPa

Resolution: 0,1 Pa

Uncertainty: $\pm 1\%$ read value, lowest $\pm 1,5\text{Pa}$

95% coverage probability in non condensing, non moist air, $<80\%RH$, non aggressive gases.

Position dependence: typ. $\pm 0,6\text{Pa}$

Operating temperature: 0...+50°C

Battery: 2 x 1,5V IEC LR6, AA


Size: 180x36x82mm

Weight: 380g

The user should correct the measured values with the correction on the calibration protocol to obtain stated accuracy. Recommended calibration interval is 1 year.

3. Start of instrument

- When starting the instrument (ON/OFF-button), the display shows the battery voltage and the version number of the firmware. After one second it goes to measuring mode.
- If the voltage should drop below 1.8 V, the symbol for low battery is shown. If the voltage should drop below 1.6 V, the instrument can't be turned on.



- **Calibrate to zero**

By pressing short on **UNIT** SwemaMan 60 is set to zero. Make sure that you have zero differential pressure connected and that you don't move the instrument during zeroing.



- **Pressure or Air velocity**

Press on UNIT for at least 3 seconds to shift between Pa, m/s or fpm. (If the differential pressure is higher than 5050 or lower than -303 Pa the display blinks due out of instrument measuring range.) To measure air velocity (m/s or fpm) connect a pitot static pipe. Selected unit will be used next time you turn the instrument on.



4. Calculation of air velocity

Air velocity is calculated from the formula:

$$v = \sqrt{\frac{2 \cdot \Delta P}{\rho}}$$

ΔP = dynamic pressure = stagnation pr.-static pressure (Pa)

$$\rho = \text{density of air} = 1.293 \cdot \frac{B \cdot 273}{1013 \cdot (273 + t)} \quad (\text{kg/m}^3)$$

B = barometric pressure (calculated value 1013hPa)

t = Air temperature (calculated value 20°C)

Use the correction table on the backside of the instrument when measuring at different temperatures and barometric pressures.

5. Data transfer to PC

Connect SwemaMan 60 to a computer by using "PC-cable to SwemaMan" (Part no: 763040). The PC-cable has a RS232 connection so connect it to a free COM-port on the computer. If the computer hasn't a COM-port use a USB-adapter (Part no: 583225).

To transfer data use a terminal software for example "Hyperterminal" or "Teraterm" (Teraterm can be downloaded at www.swema.com).

Set in the terminal software which COM-port the instrumentet is connected to. Use following settings in the software for the COM-port:

Bits per second: **9600**
Data bits: **8**
Parity: **None**
Stop bits: **1**
Flow control: **Hardware**

Press **ENTER** on the computer-keyboard and you get a calibration protocol. In the calibration protocol the values between -300 and 500 have one decimal but are printed without a decimal comma. Temp is the surrounding temperature at calibration with 2 decimals, without comma.

Press **Space** and the measurement data is printed on the screen (the same unit that is shown in the display). The instrument shows only one value at a time Pa (with 1 decimal), m/s (with 1 decimal) or fpm (without decimals).

6. Alter settings by PC

When SwemaMan 60 is connected to a PC it is possible to change some settings.

Press **%M ENTER ENTER** to enter settings menu:

[P] Point	0
[S] Shut	0
[T] Time constant	0
[V] Valve	0

Press **P** or **p** to change between "," (comma) and "." (point) as indicating decimal (comma = 0) or (point = 1).

This is for PC printouts of measured value. Confirm with **ENTER**.

Press **S** or **s** to change shut off time in minutes. Select 0 to disable auto shut off. Confirm with **ENTER**

Press **T** or **t** to change display time constant. The display is updated every 0,25 seconds (T=0) or 0,5 seconds (T=1) or 2 second (T=2) or 8 seconds (T=3). Confirm with **ENTER**

V is only used if Swema has installed a valve (short-circuits the pressure automatically). Normally there are no valve installed and the value should be 0.

Exit the menu by pressing **% ENTER**.

